

██████████, Aquaculture Tech.

November 9, 2017

Interviewer: Kessina Lee

Note Taker: ██████████

Cooke Aquaculture Lawyers: Diane Myers, Tom McConville, Charles Ha

August 2017 Incident:

- Saturday 3 – 4 anchor lines broke and Mr. ██████████ called ██████████
- Mr. ██████████ works on Site 3 but was on Site 1 at the time.
- In August when Site 2 incident occurred ██████████ and ██████████ came to the site Saturday, others arrived Sunday.
- Mr. ██████████ did not see Site 2 move, but did see the walkways buckling, the structure bending, and twisting.
- Mr. ██████████ is currently working on harvesting Site 3 on Tuesday and Sunday, the next scheduled harvest may be in December.
- When the incident happened the sea state was flat with the current running strong.
- Hinges for the walkways are on each corner, they do not run the entire width of the walkway.
- During the Site relocation (in the past) boats were used to reposition the structure, tugs were not involved.
- Mr. ██████████ daily duties include feeding, net washing, and watching the fish feed to know when to stop adding feed.
- There are 12 pens at Site 3, 10 at Site 2, 8 at Site 1.
- Harvesting takes time, it starts in July and ends in December.
- Fish weigh 4 kilograms at harvest.